

Urgent Medical Device Correction

Pump Weld Update for HeartWare™ Ventricular Assist Device (HVAD™)

Model	Product Description
1103	HVAD™ Pump Implant Kit
1104	HVAD™ Pump Implant Kit
1104JP	HVAD™ Pump Implant Kit
MCS1705PU	HVAD™ Pump Implant Kit

27 July 2022

Attention: Risk Management Director and O.R Materials Management

CC: The Chairman Medical Board and relevant Head of Departments


Dear Physician and Healthcare Professional:

Medtronic is providing this letter as a follow-up to our 27 April 2022 communication titled "Urgent Medical Device Correction" (attached), which communicated a pump weld non-conformance with the HeartWare™ Ventricular Assist Device (HVAD™) System where (3) pumps were identified to have an impeller rotating non-concentrically and contacting the center post of the pump (see Figure 1: Pump Assembly). Medtronic's investigation was not able to conclusively isolate this issue to a specific subset of pumps. This communication provides updated information on the number of events, additional event details, and root cause.

There are no new patient management recommendations since the 27 April 2022 communication.

Consistent with the April communication, **routine prophylactic explant of the HVAD device is not recommended**, as risks associated with explantation may outweigh the potential benefits of continued HVAD therapy.

Figure 1: Pump Assembly



Summary of Confirmed Complaints

Since the 27 April communication, Medtronic has received one (1) additional confirmed complaint related to this non-conformance, for a total of four (4) complaints. In all four complaints, each patient underwent a pump exchange due to suspicion of pump thrombus; however, no evidence of thrombus was found. Inspection of the explanted pumps revealed evidence of the impeller contacting the center post due to non-concentric rotation, consistent with corrosion of the center post magnet. Two (2) deaths were reported in association with these four complaints: in one case the patient underwent a cardiac transplant two months after the pump exchange and died one month after the transplant; in the other case the patient died three weeks after the VAD exchange.

Investigation of the four (4) complaints and bench testing of simulated corroded magnets indicates that an abnormal noise or vibration, commonly described as a “grinding” sound, was heard by either the patients or their clinicians. The grinding sound did not resolve after treatment for thrombus and is a likely initial indication that the impeller is contacting the center-post due to nonconcentric rotation. Over time, transient power spikes occurred on the logfiles causing [High Watt] alarms. This is unlike the gradual steady increase in power consumption typically seen with pump thrombus.

Although the root cause of the four complaints referenced above has been confirmed by analysis of the returned pumps, Medtronic continues to investigate complaints of suspected pump weld non-conformances.

Patients with affected devices may present with signs and symptoms that resemble pump thrombus. It is not known if a patient’s pump with this issue will present with the same signs/symptoms. In all four (4) instances the following were consistently encountered:

- Suspected Thrombus
- High Watt Alarms
- Grinding sound

The table below provides a summary of the four (4) confirmed complaints provided to Medtronic.

	Manufacturing Date	Implant Duration	Reported Signs and Symptoms
Complaint 1	Dec 2017	25 months	<ul style="list-style-type: none">• Suspected thrombus• High watt alarms• Grinding sounds• Vibration• Reported Patient Symptoms: fatigue, light-headedness and dizziness, shortness of breath
Complaint 2	Jan 2018	28 months	<ul style="list-style-type: none">• Suspected thrombus• Grinding sounds

			<ul style="list-style-type: none"> • High watt alarms • Elevated LDH level • Reported Patient Symptoms: dark urine
Complaint 3	May 2018	35 months	<ul style="list-style-type: none"> • Suspected thrombus • Grinding sounds • High watt alarms • Elevated LDH level • Reported Patient Symptoms: unknown
Complaint 4	April 2019	30 months	<ul style="list-style-type: none"> • Suspected thrombus • Grinding sounds • High watt alarms • Low flow alarms • Elevated LDH level • Reported Patient Symptoms: unknown

Summary of Root Cause Investigation

As a part of the investigation, Medtronic conducted a broad search of historical complaints and product returns to determine if there were additional pumps with suspected thrombus that may have a previously undetected corroded center-post magnet. As of JUL 2022, Medtronic completed an analysis of over 747 complaints from our returned product archives. Of those 747 complaints, Medtronic conducted a further analysis on 54 explanted pumps that had been returned to our analysis lab from 2012 to 2022. The returned pumps had allegations of thrombus, or a report of grinding sound or vibration. No additional occurrences of center-post magnet corrosion were found.

The investigation has determined that the occurrence of a weld crack is the result of a combination of factors that may include the initial presence of contamination in the weld area from previously applied substances as part of the manufacturing process, the misalignment of the cap and housing prior to welding, or the depth/thickness of the weld. Medtronic’s investigation employed multiple methods to isolate the issue to a specific subset of pumps including quantifying weld thickness, alignment indicators, and visual indications of contamination using over 8000 digital photos. Medtronic has found that there is not enough data available to conclusively isolate this issue to a specific subset of pumps.

Patient Management Recommendations

Consistent with the 27 April 2022 communication, routine prophylactic explant of the HVAD device is not recommended, as risks associated with explantation may outweigh the potential benefits. Physicians should make the decision regarding explant and exchange of the HVAD pump on a case-by-case basis

(is the patient a candidate for pump exchange, heart transplant, or pump explant for recovery), considering the patient's clinical condition and surgical risks. If a pump is explanted or exchanged for any reason, please return it to Medtronic for further analysis.

For patients presenting with any of the above signs and symptoms consider whether the clinical presentation could be due to a pump thrombus and treat accordingly. Please contact your local Medtronic field representative to provide details regarding the sequence of events and patient outcomes.

If patients present with these signs and symptoms listed above, please upload and submit all .csv logfiles to <https://autologs.medtronic.com>. Once on the website, please ensure to select the HVADlogs radio button and select "Urgent". Your local Medtronic field representative can assist with further logfile submission and analysis questions. An immediate answer to the etiology of the issue may not always be possible. Medtronic will analyze these logfiles and any other signs/symptoms as part of the ongoing investigation.

Customer Instructions

Medtronic records indicate that your site has patients that may still be on support; we request that you do the following:

- This notice must be shared with all those who need to be aware within your organization or any organization where patients have been transferred.
- An optional Patient Template letter will be shared with you, for your patients to ensure they are informed of the latest information on the internal pump weld defect.
- Please complete the enclosed Customer Confirmation Form and hand back or scan then email to your local Medtronic field representative.

Adverse reactions or quality problems experienced with this product should be reported to your local Medtronic field representative

Medtronic will notify all applicable regulatory agencies of this matter. Medtronic remains dedicated to further investigation of this issue and will continue to monitor device performance to ensure we meet your needs and those of your patients. If you have any questions, please contact your local Medtronic field Representative. For any additional questions you can reach out to the Medtronic Office of Medical Affairs at rs.mcsmedicalaffairs@medtronic.com.

Sincerely,



Medtronic QRA Lead
Singapore & Malaysia

DocuSigned by:



Signer Name: Chloe Tan

Signing Reason: I approve this document

Signing Time: 27 July 2022 | 05:56 SGT

90D0724C9B1C402A99B286449A1644B8

Medtronic QRA Lead

Indochina & Frontier Markets Plus



Medtronic International, Ltd. (Singapore Branch)

(Co.Reg.No. S98FC5604C)

50 Pasir Panjang Road

#04-51

Mapletree Business City

Singapore 117384

Tel: 165.6870.5300

Fax: 65.6482.0300

www.medtronic.com



14400 NW 60th Avenue

Miami Lakes, FL 33014

USA

www.heartware.com

Customer Confirmation Form

Urgent Medical Device Correction

Medtronic HeartWare™ Ventricular Assist Device (HVAD) system

For completion by Medtronic Customers Only - Please complete all fields below and return all pages immediately

Medtronic is asking that you sign and date this form to acknowledge receipt of the enclosed letter.

Note: The addressee may continue to receive reminders of this notice until a response is received.

Customer Contact Details	Medtronic Contact Details
Distributor/HCP/Patient name:	Name:
	Contact:
Address:	Email:
Phone no:	
E-mail:	

By signing this form, I confirm that I have read the Urgent Medical Device Correction Notification Letter, dated **27 July 2022**, from Medtronic regarding the HeartWare™ Ventricular Assist Device (HVAD) system listed above and will take appropriate action.

Name (print): _____ Signature: _____ Stamp: _____ Date:

For questions, contact your Medtronic Field Representative.