

August 11, 2022

FIELD SAFETY NOTICE for HAMILTON-C6 end customers/distribution partners

Temporary failure of the HAMILTON-C6 ventilator display

- Recipients:**
- All health care facilities using HAMILTON-C6 ventilators (intensive care units, intermediate care units, emergency rooms, long-term acute care hospitals, or in the recovery room).
 - All distributors of HAMILTON-C6 ventilators and their service engineers.
 - Given the urgency of this field safety notice we ask you to take the required action and send confirmation of this to Hamilton Medical AG within 30 working days after receipt of this information.

Product / HAMILTON-C6 (PN 160021)

**Software
concerned:**

All versions

Dear end customer/distribution partner,

Hamilton Medical AG was asked by the Swiss health authority Swissmedic to inform all of our end customers about the following:

In very rare cases, the backlight of the HAMILTON-C6 display may fail. This is attributable to a reset of the HMI controller (HMI reset) which causes the display to fail for 2–3 seconds. The device's ventilation function is not affected by this.

Please confirm with your signature on the enclosed confirmation sheet (page 3) that you, as an end customer/distribution partner, have received this FSN and have taken the actions specified by us.

At this time, a repair to resolve the malfunction is not available. Therefore, we have to ensure that all end customers are notified of this and understand that the device's ventilation function is not affected by the HMI reset and that it is not necessary to replace the ventilator. This information is also included in the operating instructions. However, we believe that it is possible that the provided information may be missed in such a situation.

Reason for the field safety notice:

With this notice, we would like to inform you that temporary display failures on the HAMILTON-C6 may occur during ventilation.

What does this malfunction look like?

In very rare cases, the backlight of the ventilator display may fail. This causes the display to turn black for 2–3 seconds; however, the display lights back up when the backlight turns on again.

Is there a risk to patients?

The monitor and the ventilation unit function as two independent units. Therefore, the ventilation unit's functionality is guaranteed even if a temporary monitor failure should occur.

The device automatically resolves this malfunction by performing an HMI reset. The monitor backlight then functions properly again. This process does not take more than 3 seconds and is automatically performed by the device WITHOUT interruptions in ventilation.

The application software displays this error as **1246033: taLLS_hmiWatchdogTimeout**.

How can the end customer ensure that the device continues to ventilate the patient?

The user can monitor the key device functions by keeping an eye on the status indicator lamps located on the upper front edge of the ventilation unit. This is described in Section 2.2.1.1 of the Operator's Manual and is also pictured again in the following image. If the lamp with the lung icon lights up "green," the device is ventilating the patient in accordance with the specified parameters and the device does not need to be replaced.

***How can you record a device failure?***

Should the display temporarily turn dark, you can acknowledge the error message "**1246033: taLLS_hmiWatchdogTimeout**" and continue to use the ventilator. Service is not required in this specific case. The error that occurred is logged by the device and can be reviewed the next time the unit is serviced.

We apologize for any inconvenience this may cause.

**Actions to be taken
by distribution
partners:**

- Please sign the enclosed sheet confirming that you have received the FSN and have passed it on to your end customers.
- Please inform Hamilton Medical AG's Technical Support of any such malfunctions, indicating the affected system, so that we can communicate these to the authorities on a quarterly basis.

**Actions to be taken
by end customers:**

- Please sign the enclosed sheet confirming that you have received and understood the FSN. Also, please continue to notify your local distribution partner of any cases of the aforementioned malfunction. No further action on your part is required.


Please note that the first point of contact in this matter is always the local distribution partner.

Manufacturer: Hamilton Medical AG
Via Crusch 8
CH-7402 Bonaduz
Switzerland

Contact: Should you have any questions please do not hesitate to get in contact with us.

Hamilton Medical AG
Technical Support
Parc Industrial Vial 10
CH-7013 Domat/Ems
Switzerland
Tel. +41 58 610 10 20
e-mail: techsupport@hamilton-medical.com

We appreciate your support in this matter and sincerely regret any inconvenience you may experience as a result of the issue described above.



Vigilance Department
Hamilton Medical AG

Jürg Marugg
Medical Technical Support
Hamilton Medical AG

Please keep this information sheet with your HAMILTON-C6 Operator's Manual.