

**Atellica® UAS 800 Urine Sediment Analyzer  
Atellica® 1500 Automated Urinalysis System**

**Misidentification of Sample IDs**

---

Our records indicate that your facility may have received the following product:

**Table 1. Affected Products**

Product Description	Siemens Material Number (SMN)	Unique Device Identification (UDI-DI)	Software Version
Atellica UAS 800 Urine Sediment Analyzer Atellica 1500 Automated Urinalysis System	11065004	00630414001357	All versions up to and including v4.0.400

**Reason for Urgent Field Safety Notice**

The purpose of this communication is to inform you of a potential issue with the product indicated in **Table 1** above and provide instructions on actions that your facility must take.

Siemens Healthcare Diagnostics Inc. has confirmed an issue that has the potential to misidentify samples when ALL the following specific conditions are met:

- the cuvettes run out after the start of or in the middle of sample analysis, AND
- the user presses the “Continue” button within 3 seconds of the button enabling to reinitiate analysis after cuvette replacement, AND
- the barcode reader does not detect a barcode (either due to a non-existent or poor quality barcode).

When all three of these conditions are met, the instrument assigns the next two consecutive tubes the same Sample ID and shifts the Sample IDs for the remaining tubes in that run. The misidentified sample ID may potentially lead to the display of incorrect patient results. The issue can also occur while running Quality Controls (QC) if cuvettes are depleted during a QC run.

This is due to a software issue that prematurely enables the “Continue” button, disrupting the homing of the sample rack.

### **Risk to Health**

The Atellica UAS 800 software versions up to and including v4.0.400 were confirmed to display incorrect results without alerting the user when testing patient samples. This could lead to incorrect

## Misidentification of Sample IDs

or delayed diagnosis. This issue can also occur during QC; however, it would be obvious to the user and require repeat QC analysis.

Mitigations include that several conditions need to be met for the issues to occur, deviation from historical results, and discordance from the clinical presentation of the patient. Additionally, when analyte abnormalities are identified, especially those discordant from presentation, confirmatory testing is often completed prior to acute management.

### Actions to be Taken by the Customer

- Please review this letter with your Medical Director.
- To avoid this issue, please perform the following:
  - Ensure an adequate number of cuvettes are installed prior to initiating analysis.
  - Wait to press the “Continue” button for at least 3 seconds after the sample rack homes into position, or when the barcode reader is no longer illuminated.
  - Use sample tubes with good quality barcodes, as this will automatically register the presence of a tube without the system having to wait 3 seconds before it assigns an ID.
- If you are a distributor, please ensure your customers receive this UFSN letter.
- Complete and return the Field Correction Effectiveness Check Form attached to this letter within 10 working days.

Please retain this letter with your laboratory records and forward this letter to those who may have received this product.

This issue will be resolved with the release of the next software version on the Atellica UAS 800 analyzer. The release of the next software version will be announced as soon as it becomes available.

We apologize for the inconvenience this situation may cause. If you have any questions, please contact your Siemens Healthineers Customer Care Center at 1800-815-508 or your local Siemens Healthineers technical support representative.

### Additional Information

Atellica UAS 800 and Atellica 1500 are trademarks of Siemens Healthcare Diagnostics Inc.

# Misidentification of Sample IDs

## FIELD CORRECTION EFFECTIVENESS CHECK

### Misidentification of Sample IDs

This response form is to confirm receipt of the enclosed Siemens Healthcare Diagnostics Urgent Field Safety Notice POC 24-007.A.OUS dated January 2024 regarding Atellica UAS 800 / Atellica 1500 Misidentification of Sample IDs. Please read the below question and indicate the appropriate answer.

Return this completed form to Siemens Healthcare Sdn Bhd as per the instructions provided at the bottom of this page.

1. I have read and understood the UFSN instructions provided in this letter. Yes  No

Name of person completing questionnaire: \_\_\_\_\_

Title: \_\_\_\_\_

Institution: \_\_\_\_\_ Instrument Serial Number: \_\_\_\_\_

Street: \_\_\_\_\_

City: \_\_\_\_\_ State: \_\_\_\_\_

Phone: \_\_\_\_\_ Country: \_\_\_\_\_

Customer Sold To #: \_\_\_\_\_ Customer Ship To #: \_\_\_\_\_

Please send a scanned copy of the completed form via email to [fscareportingunit.my@siemens-healthineers.com](mailto:fscareportingunit.my@siemens-healthineers.com)

If you have any questions, contact your local Siemens Healthineers technical support representative.